


LEVEL SENSOR SS

MOUNTING INSTRUCTIONS

Step 4:

Assemble into gasket & sensor, pay attention that directions of sensor's wire and gasket gap are the same (Figure. 4)



Step 5:

Fix the screw per "diagram of star pattern" firmly, and check whether they are in connecting gasket, done (Figure. 5)




Figure. 5



LEVEL SENSOR S5

MOUNTING INSTRUCTIONS

Mod. S5-A

240/30 Ohm

12/24 V

Code: 27.160.xx

Mod. S5-E 00/190 Ohm

12/24 V

Code: 27.161.xx


Applicable to tank w/o flange assembly

Preparation: 1. Tool: $4.0 \text{mm} / \frac{1}{8} \text{ drill}$, $40 \text{mm} / 1 \frac{1}{2} \text{ opener}$, pencil, electric hand drill.

2. Empty tank, clean tank with water, keep filler open.

Step 1:

Place gasket in the required hole area in tank, draw 1 big hole and 5 small holes by pencil .(Figure. 1)



Step 2:

Drill hole with 40mm opener (Figure. 2)

Step 3:

Drill 5 screw holes with $\oint 4.0 \sim 4.2 \text{mm} / \frac{1}{8} \text{ drill, separately (Figure. 3)}$

Note: firstly, cover the big hole, and remove chips in small hole anytime, to avoid them drop into tank.

